

Restoring Your Watch
NEW 12/02/2011 6105-8119 SEIKO DIVE RESTORATION



THE NEW GSW GSWW MWB PICTURE GALLERY



MilitaryWatchBox.Com

FEB 20122 SEIKO 6105-8119 RESTORES

1000 Restorations

FEB 2012 6105-8119 SEIKO DIVE RESTORE

NEW 12/02/2011 6105-8119 SEIKO DIVE RESTORE

MAY 13, 2010 4 SEIKO DIVE RESTORE

JULY 1 2010 NEW DIVE iRESTORES AND SEIKO CHRONO

ROLEX REPAIR 3135 31 JEWEL 5 ADJ AUTOMATIC MOVEMENT



ROLEX MAIN SPRING FOR 3135
31 JEWEL AUTOMATIC



ROLEX MAIN SPRING FOR 3135

31 JEWEL AUTOMATIC



3135 31 JEWEL AUTOMATIC ADJ 5 POS



REMOVE ROTOR



REMOVE ROTOR ASSEMBLY



MAIN SPRING UNDER GOLD RACHET WHEEL
REMOVE RACHET WHEEL



REMOVED BRIDGE



BRIDGE AND RACHET WHEEL



LIFT OUT MAIN SPRING BARREL



REMOVING BALANCE OF PARTS FOR FULL CLEAN AND SERVICE
[NOTE: NOT NECESSARY IF YOU JUST WANT TO CHANGE MAIN SPRING]



MAIN SPRING BARREL




OPENED
NOTE THE SPRING IS BROKEN
ARBOR STILL ATTACHED TO BROKEN PORTION



ARBOR REMOVED
SPRING REMOVED



NEW MAIN



AUTOMATIC GREASE



SYNTHETIC OIL



HAND INSTALLING MAIN



HAND INSTALLING MAIN



BARREL WITH NEW SPRING



BACK TOGETHER
AFTER FULL TEAR DOWN CLEAN & LUBE



WE DISCOVERED A PROBLEM WITH ROTOR ASSEMBLY



WE TEAR IT DOWN



CENTER WHEEL IS WORN
LOCK IS WORN



WE REMOVE & REPLACE LOCK WITH USED PIECE
ALSO CENTER WINDING WHEEL



HERE WE ARE TESTING



PERFECT



ROTOR ASSEMBLY IS PLACED BACK ON



DATE WHEEL IS PLACED BACK ON



ROTOR BACK ON



**BIKE
WORKS**

**BIG
MARQUISE**

[About Custom Work](#) | [Services & Products](#) | [Studio Pics](#) | [Directions](#)
[GoldSmithWatchWorks](#) | [GoldSmithTraining](#) | [eBay.GoldSmithWorks](#) | [GSWAuctions](#)
[Appraisals](#) | [MilitaryWatchBox.Com](#) | [Wax Molds](#) | [Estimate](#) | [Bridal](#) | [CadCam](#)